



Concrete Protection & Restoration

1101 Wilson Boulevard

Garage Repairs

Problem

The parking garage located at 1101 Wilson Boulevard was in need of concrete repairs throughout nine elevated levels. Repairs included concrete restoration, crack repair, full depth concrete repairs, soffit repairs, installation of vehicular traffic coating, and other miscellaneous work associated with its garage restoration.

Solution

- ◇ Full depth and partial depth concrete slab repairs
- ◇ Concrete column and wall repairs
- ◇ Structural concrete beam repairs
- ◇ Removal and replacement of existing traffic coating
- ◇ Installation of new drains and pipping
- ◇ Chemical grout injection on leaking wall cracks
- ◇ Restripe of coated levels and installation of new traffic control barriers

Location

Arlington, Virginia

Project Size


\$3,000,000.00

Owner

Monday Properties

Engineer

Thornton Tomasetti



Concrete Protection & Restoration
Saving the life of concrete!

2811 Lord Baltimore Drive
Baltimore, MD 21244

601 NE 44th Street
Oakland Park, FL 33334

www.concretecpr.com
Toll Free: 800-452-3137
E-mail: info@concretecpr.com